



Overview: Part of spill impact on 12" Imo River–Ogale Pipeline Right of Way at Uzuaku. Picture was taken during the Initial Site Visit of 2nd January 2018.



Close-up: Illegal Fittings on 12" Imo River–Ogale Pipeline at Uzuaku. Picture was taken during Joint Investigation of 4th January 2018.