


Overview: Part of spill impact on 20" Rumuekpe-Nkpoku Pipeline at Ibaa. Picture was taken during Joint Investigation of 22nd December 2017.



Close-up: Drilled Hole on 20" Rumuekpe-Nkpoku Pipeline at Ibaa. Picture was taken during Joint Investigation of 30th December 2017.