



Overview: Part of spill impact on 28" Nkpoku- Bomu Pipeline Right of Way at Eteo. Picture was taken during Joint Investigation of 19<sup>th</sup> December 2017.



Close-up: Illegal Fittings on 28" Nkpoku- Bomu Pipeline at Eteo. Picture was taken during Joint Investigation of 19<sup>th</sup> December 2017.