



Overview: Part of spill impact on 12" Imo River2 – Ogale Pipeline Right of Way at Odagwa. Picture was taken during Joint Investigation of 21st February 2017.



Close-up: Illegal fitting on 12" Imo River2 – Ogale Pipeline at Odagwa. Picture was taken during Joint Investigation of 21st February 2017.