




Overview: Part of spill impact on 24" Trans-Escravos Pipeline at Ogidigben. Picture was taken during Joint Investigation of 9<sup>th</sup> March 2017.



Close-up: 6" valves illegally attached on 24" Trans-Escravos Pipeline at Ogidigben. Picture was taken during Joint Investigation of 9<sup>th</sup> March 2017.