



Overview: Part of spill impact 12" Imo River-Ogale Pipeline Right of Way at Umuololo. Picture was taken during Joint Investigation of 4<sup>th</sup> June 2017



Close-up: Illegal fitting on 12" Imo River-Ogale Pipeline at Umuololo. Picture was taken during Joint Investigation of 4<sup>th</sup> June 2017.