



Overview: Part of spill impact on 6" Imo River Well 59T Flowline at Owaza. Picture was taken during Joint Investigation of 12th January 2017.



Close-up: Illegal fitting on 6" Imo River Well 59T Flowline at Owaza. Picture was taken during Joint Investigation of 12th January 2017.