



Overview: Part of spill impact on Agbaya Well 1 Wellhead at Ogbotobo. Picture was taken during Joint Investigation of 17th January 2017.



Close-up: 4" illegally attached bunkering hose on Agbaya Well 1 Wellhead at Ogbotobo. Picture was taken during Joint Investigation of 17th January 2017.