



Overview: Part of spill impact 12" Imo River-Ogale Pipeline at Komkom. Picture was taken during Joint Investigation of 10th March 2017



Close-up: Leaking Illegal fittings on 12" Imo River-Ogale Pipeline at Komkom. Picture was taken during Joint Investigation of 10th March 2017