



Overview: Part of spill impact on 4" Obele-Ibaa Pipeline Right of Way at Ibaa. Picture was taken during Joint Investigation of 21st March 2017.



Close-up: 1st of 5 Hacksaw cuts on 4" Obele-Ibaa Pipeline at Ibaa. Picture was taken during Joint Investigation of 21st March 2017.



Close-up: 2nd of 5 Hacksaw cuts on 4" Obele-Ibaa Pipeline at Ibaa. Picture was taken during Joint Investigation of 21st March 2017.



Close-up: 3rd of 5 Hacksaw cuts on 4" Obele-Ibaa Pipeline at Ibaa. Picture was taken during Joint Investigation of 21st March 2017.



Close-up: 4th of 5 Hacksaw cuts on 4" Obele-Ibaa Pipeline at Ibaa. Picture was taken during Joint Investigation of 22nd March 2017.



Close-up: 5th of 5 Hacksaw cuts on 4" Obele-Ibaa Pipeline at Ibaa. Picture was taken during Joint Investigation of 22nd March 2017.