



Overview: Part of spill impact on 24"Trans-Ramos Pipeline Right of Way at Odimodi. Picture was taken during Joint Investigation of 2<sup>nd</sup> August 2017.



Close-up: Excavated Pit with residual oil seepage on 24"Trans-Ramos Pipeline at Odimodi. Picture was taken during Joint Investigation of 2<sup>nd</sup> August 2017.