



Overview: Part of spill impact on 12" Imo River - Ogale Pipeline Right of Way at Komkom. Picture was taken during Joint Investigation of 12th July 2017.



Close-up: Leaking illegal fitting on 12" Imo River-Ogale Pipeline at Komkom. Non-leaking fitting subject to another Joint Investigation Visit.