




Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline Right of Way at B-Dere. Picture was taken during Joint Investigation of 25th July 2017.



Close-up: Illegal fitting on 28" Nkpoku-Bomu Pipeline at B-Dere. Picture was taken during Joint Investigation of 25th July 2017.