




Overview: Part of spill impact on 12" Oguta-Egbema Pipeline Right of Way at Oguta. Picture was taken during Joint Investigation of 2nd August 2017.



Close-up: Attempted Drilled Hole on 12" Oguta-Egbema Pipeline at Oguta. Picture was taken during Joint Investigation of 2nd August 2017.