


**Overview:** Part of spill impact on Belema Flow Station at Belema. Picture was taken during Joint Investigation of 1<sup>st</sup> Aug 2017.



**Close-up:** Original Position of the Ruptured Flexible Discharge Spool Piece on Belema Flow Station at Belema. Picture was taken during Joint Investigation of 1<sup>st</sup> Aug 2017.



Close-up: Ruptured Flexible Discharge Spool Piece on Belema Flow Station at Belema. Picture was taken during Joint Investigation of 1<sup>st</sup> Aug 2017.