



Overview: Part of spill impact on 4" Adibawa Well 4 & 7 flowline Right of Way at Edagberi. Picture was taken during Joint Investigation of 5th July 2017.



Close-up: No spill point found on 4" Adibawa Well 4 & 7 flowline at Edagberi. Picture was taken during Joint Investigation of 15th January 2018.