



Overview: Part of spill impact on 6" Imo River 3 Well 37L Flowline at Igiriukwu-Owaza. Picture was taken during Joint Investigation of 21st March 2017.



Close-up: Hacksaw cut on 6" Imo River 3 Well 37L Flowline at Igiriukwu-Owaza. Picture was taken during Joint Investigation of 21st March 2017.