



Overview: Part of Spill impact on 12" Imo River – Ogale Pipeline Right of Way at Uzuaku Picture was taken during Joint Investigation of 29th March 2017.



Close-up: Drilled hole on 12" Imo River – Ogale Pipeline at Uzuaku Picture was taken during Joint Investigation of 2nd April 2017.