




Overview: Part of spill impact on Agbada 2 Well34S 4" Flowline Right of Way at Omueke .
 Picture was taken during initial site visit on 29th March 2017.



Close-up: Cut section on Agbada 2 Well34S 4" Flowline at Omueke . Picture was taken during
 initial site visit on 29th March 2017.