



Overview: Part of spill impact within Bonny Oil & Gas Terminal Tank Bund area at Bonny. Picture was taken during Joint Investigation of 13th April 2017.



Close-up: Spill point within Bonny Oil & Gas Terminal Tank Bund area at Bonny. Picture was taken during Joint Investigation of 7th April 2017.