



Overview: Part of spill impact on Nun River Well 15 Wellhead at Onyoma. Picture was taken during Joint Investigation of 17th November 2017.



Close-up: Position of Missing Survey Valves on Nun River Well 15 Wellhead at Onyoma. Picture was taken during Joint Investigation of 17th November 2017.