



Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline Right of Way at Norkpo. Picture was taken during the Initial Site Visit of 12<sup>th</sup> Nov. 2017.



Close-up: Illegal Fitting on 28" Nkpoku-Bomu Pipeline at Norkpo. Picture was taken during the Initial Site Visit of 13<sup>th</sup> Nov. 2017.