




Overview: Part of spill impact on 20" Kolocreek-Rumuekpe Pipeline Right of Way at Odau_Ozochi Picture was taken during Joint Investigation of 25th November 2017.



Close-up: Illegal fitting on 20" Kolocreek-Rumuekpe Pipeline at Odau_Ozochi. Picture was taken during Joint Investigation of 25th November 2017.