



Overview: Part of spill impact on 18" Assa-Rumuekpe Pipeline at Awara. Picture was taken during Joint Investigation of 24th October 2017.



Close-up: Illegal fitting on 18" Assa-Rumuekpe Pipeline at Awara. Picture was taken during Joint Investigation of 25th October 2017.