



Overview: Part of spill impact on Soku Well 22 Well Head. Picture was taken during Joint Investigation of 23rd September 2017.



Close-up: Position of Removed Bean Box cover on Soku Well 22 Well Head. Picture was taken during Joint Investigation of 23rd September 2017.