



Overview: Part of spill impact on Agbaya well 1 Wellhead at Agbayama. Picture was taken during Joint Investigation of 28th September 2017.



Close-up: Position of Stolen CCU, Bean Box and Wellhead Survey Cap on Agbaya well 1 Wellhead at Agbayama. Picture was taken during Joint Investigation of 28th September 2017.