



Overview: Part of spill impact on 16" Egbema-Assa Pipeline at Obile. Picture was taken during Joint Investigation of 12th October 2017.



Close-up: Illegal fitting on 16" Egbema-Assa Pipeline at Obile. Picture was taken during Joint Investigation of 12th October 2017.