




Overview: Part of spill impact on 28" Bomu-Bonny Pipeline at Patrick Waterside. Picture was taken during Joint Investigation of 10th April 2018.



Close-up: Illegal fitting on 28" Bomu-Bonny Pipeline at Patrick Waterside. Picture was taken during Joint Investigation of 10th April 2018.