


Overview: Part of spill impact on 18" Assa-Rumuekpe Pipeline at Ochia. Picture was taken during Joint Investigation of 21st April 2018.



Close-up: Illegal fitting on 18" Assa-Rumuekpe Pipeline at Ochia. Picture was taken during Joint Investigation of 21st April 2018.