




Overview: Part of spill impact 24"Trans-Ramos Pipeline Right of Way at Odimodi. Picture was taken during Joint Investigation of 30th May 2018.



Close-up: Corrosion on 24"Trans-Ramos Pipeline at Odimodi. Picture was taken during Joint Investigation of 30th May 2018.