



Overview: Part of spill impact on 20" Kolocreek-Rumuekpe Pipeline Right of Way at Imogu-Rumuekpe. Picture was taken during Joint Investigation of 12th June 2018.



Close-up: Illegal fitting on 20" Kolocreek-Rumuekpe Pipeline at Imogu-Rumuekpe. Picture was taken during Joint Investigation of 12th June 2018.