



Overview: Part of spill impact on Soku Well 14S Flowline at Soku. Picture was taken during Joint Investigation of 7th February 2018.



Close-up: Position of missing flowline on Soku Well 14S Flowline at Soku. Picture was taken during Joint Investigation of 7th February 2018.