




Overview: Part of spill impact on 12" Adibawa-Okordia Pipeline Right of Way at Okordia. Picture was taken during Joint Investigation of 2nd March 2018.



Close-up: Hacksaw cut on 12" Adibawa-Okordia Pipeline at Okordia. Picture was taken during Joint Investigation of 2nd March 2018.