



Overview: Part of spill impact on 12" Imo River – Ogale Pipeline Right of Way at Okohia. Picture was taken during Joint Investigation of 27th February 2018.



Close-up: Illegal fitting on 12" Imo River – Ogale Pipeline at Okohia. Picture was taken during Joint Investigation of 27th February 2018.