


**Overview:** Part of spill impact on 20" Kolocreek-Rumuekpe Pipeline at Odau. Picture was taken during Joint Investigation of 16<sup>th</sup> March 2018.



**Close-up:** Illegal fitting on 20" Kolocreek-Rumuekpe Pipeline at Odau. Picture was taken during Joint Investigation of 16<sup>th</sup> March 2018.