

Overview: Part of spill impact on 6''Obigbo North-Ogale Pipeline at Ogale. Picture was taken during Joint Investigation of 10th January 2018.



Close-up: Drilled Hole on 6''Obigbo North-Ogale Pipeline at Ogale. Picture was taken during Joint Investigation of 11th January 2018.