



Overview: Part of spill impact on 12" Imo Rive2-Ogale Pipeline Right of Way at Igiriukwu-Isi-Etithoha. Picture was taken during Joint Investigation of 11<sup>th</sup> July 2018.



Close-up: Illegal fitting on 12" Imo Rive2-Ogale Pipeline at Igiriukwu-Isi-Etithoha Picture was taken during Joint Investigation of 11<sup>th</sup> July 2018.