



Overview: Part of spill impact on Kolocreek Well-19T Flowline at Imiringi. Picture was taken during Joint Investigation of 4th July 2018.



Close-up: Leaking Disused 6" Kolocreek Well-19T Flowline at Imiringi. Picture was taken during Joint Investigation of 4th July 2018.