



Overview: Part of spill impact on Imo River Well59 Flowline at Igiriukwu. Picture was taken during Joint Investigation of 10th July 2018.



Close-up: Illegal fitting on Imo River Well59 Flowline at Igiriukwu. Picture was taken during Joint Investigation of 10th July 2018.