




Overview: Part of spill impact on 16'' Nun River-Kolocreek Pipeline Right of Way at Oporoma. Picture was taken during Joint Investigation of 14th July 2018.



Close-up: Corrosion on 16'' Nun River-Kolocreek Pipeline at Oporoma. Picture was taken during Joint Investigation of 14th July 2018..