



Overview: Part of spill impact on 12" Imo River-Ogale Pipeline Right of Way at Umuololo-Etitiuzo. Picture was taken during Joint Investigation of 18th July 2018.



Close-up: Illegal Fittings on 12" Imo River-Ogale Pipeline at Umuololo-Etitiuzo. Picture was taken during Joint Investigation of 18th July 2018.