




Overview: Part of spill impact on Agbaya well-1 Wellhead at Ogbotobo-Agbayama. Picture was taken during Joint Investigation of 31st July 2018.



Close-up: Tampered Valve on Agbaya well-1 Wellhead at Ogbotobo-Agbayama. Picture was taken during Joint Investigation of 31st July 2018.