





**Overview:** Part of spill impact on 20" Kolocreek-Rumuekpe Pipeline Right of Way at Rumuekpe. Picture was taken during Joint Investigation of 26<sup>th</sup> July 2018.



**Close-up:** Illegal fitting on 20" Kolocreek-Rumuekpe Pipeline at Rumuekpe. Picture was taken during Joint Investigation of 26<sup>th</sup> July 2018.



Close-up: Spill point on 20" Kolocreek-Rumuekpe Pipeline at Rumuekpe. Picture was taken during Joint Investigation of 25<sup>th</sup> July 2018.