




**Overview:** Part of spill impact on 12" ImoRiver-Ogale Pipeline Right of Way at Ogale. Picture was taken during Joint Investigation of 2<sup>nd</sup> August 2018.



**Close-up:** Drilled Hole on 12" ImoRiver-Ogale Pipeline at Ogale. Picture was taken during Joint Investigation of 2<sup>nd</sup> August 2018.