



Overview: Part of spill impact on 20" Rumuekpe-Nkpoku Pipeline Right of Way at Mbodo-Aluu. Picture was taken during Joint Investigation of 19<sup>th</sup> July 2018.



Close-up: Illegal fitting on 20" Rumuekpe-Nkpoku Pipeline at Mbodo-Aluu. Picture was taken during Post Joint Investigation of 20<sup>th</sup> July 2018.