




Overview: Part of spill impact on 16" NunRiver-Kolocreek Pipeline Right of Way at Otuegwe. Picture was taken during Joint Investigation of 21<sup>st</sup> July 2018.



Close-up: Illegal fitting on 16" NunRiver-Kolocreek Pipeline at Otuegwe. Picture was taken during Joint Investigation of 21<sup>st</sup> July 2018.