


Overview: Part of spill impact on 20" Rumuekpe - Nkpoku Pipeline at Ibaa. Picture was taken during Joint Investigation of 18th July 2018.



Close-up: Drilled Hole on 20" Rumuekpe - Nkpoku Pipeline at Ibaa. Picture was taken during Joint Investigation of 19th July 2018.