




**Overview:** Part of spill impact on 10'' DiebuCreek– Nun River Pipeline Right of Way at Oporoma. Picture was taken during Joint Investigation of 18<sup>th</sup> June 2018.



**Close-up:** Hacksaw Cuts on 10'' DiebuCreek– Nun River Pipeline at Oporoma. . Picture was taken during Joint Investigation of 22<sup>nd</sup> June 2018.