


Overview: Part of spill impact on 14" Okordia-Rumuekpe Pipeline Right of Way at Ula-Ikata. Picture was taken during Joint Investigation of 20th June 2018.



Close-up: Illegal fitting on 14" Okordia-Rumuekpe Pipeline at Ula-Ikata. Picture was taken during Joint Investigation of 26th June 2018.