



Overview: Part of spill impact on 10" Diebucreek-Nunriver Pipeline Right of Way at Oporoma. Picture was taken during Pre-Joint Investigation Visit of 20th June 2018.



Close-up: Multiple Leaking Hacksaw Cuts on 10" Diebucreek-Nunriver Pipeline at Oporoma. Picture was taken during Joint Investigation of 22nd June 2018.